

# 2018 ANNUAL INSPECTION REPORT

Byproduct Storage Area B


St. Johns River Power Park

Submitted to:

JEA/St. Johns River Park

11201 New Berlin Road Jacksonville, FL 32226 USA

Submitted by:



# **Distribution List**

JEA

Hopping Green & Sams



i

# **Table of Contents**

## **FIGURES**

Figure 1 Site Location Map

Figure 2 Byproduct Storage Area B Grid Location Map



ii

# INTRODUCTION

Golder Associates Inc. (Golder) conducted the coal combustion residual (CCR) landfill annual inspection for Byproduct Storage Area B (BSA-B) at the St. Johns River Power Park (SJRPP). The inspection, conducted on December 5, 2018, and this report are intended to meet the requirements of 40 CFR §257.84. Golder's inspection was performed by Samuel Stafford, PE.

The Phase I development of BSA-B is located approximately 1.5 miles northeast of the SJRPP main entrance in northeastern Duval County, Jacksonville, Florida (see Figure 1).

#### REVIEW OF AVAILABLE INFORMATION

In accordance with §257.84(b)(1), Golder reviewed available information regarding the status and conditions of BSA-B include operating record documents. The documents reviewed included:

- Technical Submittal, Hydrogeological and Geotechnical Site Evaluation, Conceptual Design Drawings, dated April 2007 (including associated responses to comments), Golder project number 043-2650.
- Area B Byproduct Storage Area Phase I Operations Plan, September 2014, Golder project number 113-82588.
- Run-on and Run-off Control Plan, Byproduct Storage Area B, October 2015, Golder project number 15-26356.
- Operating records: SJRPP weekly inspection reports.

#### INSPECTION SUMMARY

Golder conducted a visual inspection of BSA-B on December 5, 2018. The inspection considered cover conditions, exterior slope conditions, erosional conditions, vegetative conditions, stormwater management conditions, placement of CCRs, slope stability, and any other signs of distress or malfunction.

#### CHANGES IN GEOMETRY

The primary changes in geometry of BSA-B since the past annual inspection are due to CCR placement in the central portion of BSA-B and relocation of CCR from the western portion of the Phase I footprint to the northern slope of BSA-B.

#### APPROXIMATE CCR VOLUME

The volume of materials in BSA-B at the time of the inspection is estimated to be approximately 1,575,000 cubic yards based on past topographic survey data and recent disposal records.

#### STRUCTURAL WEAKNESS AND DISRUPTING CONDITIONS

No indications of actual or potential structural weakness were noted during the December 5, 2018 inspection or during the review of available information.

Conditions identified during the inspection that could have the potential to disrupt the operations of the BSA include erosion of CCRs on the northern and western slopes and the operation of the contact water pond pump station. The north and west slopes are to be reworked as additional fill materials are placed in the BSA. The contact water pump station associated with the contact water ponds has been taken off-line due to the ongoing decommissioning of SJRPP. Operations personnel will monitor the contact water levels and make necessary arrangements to transfer contact water to the facility wastewater treatment plant in the event of high contact water levels.



## **CHANGES AFFECTING STABILITY OR OPERATIONS**

Based on the December 5, 2018 inspection and review of available information, no changes from the previous inspection conducted on December 13, 2017 that may effect the operations or stability of BSA-B were observed.

### **CLOSING**

Based on the review of the available information noted above and on the December 5, 2018 field observations, Golder concludes that the design, construction, operation, and maintenance of BSA-B appears to be consistent with recognized and generally accepted good engineering standards.

Golder Associates Inc.

Samuel F. Stafford, PE Senior Project Engineer Gregory M. Powell, PhD, PE Practice Leader and Prinicpal


Dugny Mowell

SFS/GMP/ams

Golder and the G logo are trademarks of Golder Associates Corporation


G:\Projects\15-\15-26356.2\Reports\Final\2018 Annual Inspection\SJRPP BSA-B 2018 Inspection.docx





APPROVED

JPO





golder.com