



Building Community<sup>sm</sup>

This report was created using  
ThermaCAM Reporter 99,  
a software from  
FLIR Systems AB

# **Preventive Maintenance Inspection at**

## **SE Jax Sub. EL-20170706-000013**

*7/6/2017*

### **General Information**

Report consists of 1 each: Severity level #1

---

P. Traylor



## Table of Contents

| <b>Circuit</b>                 | <b>Equipment</b> | <b>Page</b> |
|--------------------------------|------------------|-------------|
| SE Jax Sub. EL-20170706-000013 | Sw. 573L         | 3           |



Inspected Equipment:

**Sw. 573L**

Operator:



P. Traylor

### Identification



|                        |                                |
|------------------------|--------------------------------|
| Station/Circuit        | SE Jax Sub. EL-20170706-000013 |
| Equipment              | Sw. 573L                       |
| Additional information | B phase clip                   |
| Date                   | 7/6/2017                       |

### Fault description



**Severity Grade**

**#1**

**Reference Temperature**

28.0°C

| Label | Value |
|-------|-------|
| SP01  | 333°C |

**Temperature Difference**

SP01

304.6°C

-

\*

-

\*

### Recommendation

**Immediate repair**

304.6C delta = 548.3F delta



# Summary of Inspection at

## SE Jax Sub. EL-20170706-000013

### List of Inspected Items

| Circuit                        | Equipment | Grade | Recommendation   |
|--------------------------------|-----------|-------|------------------|
| SE Jax Sub. EL-20170706-000013 | Sw. 573L  | #1    | Immediate repair |