

Spiral Chute wear


Liner plates direct bucket fuel discharge to conveyor belt



Replaced plate / 42 liners / and 33 side wall wear plates



The following equipment, work location photographs are provided to assist in depicting the equipment.











10.30.2014 13:57



11.14.2014 08:10




ICSUG-01-03115

341075-5-1

11.14.2014 08:11





36

LCSU6-01-0306-S

LCSU6-01-0306S

10/03/2014