

SELF-CLEANER PUMP-OUT REPORTING IN FOG BMP

Standard Operating Procedure

This document is designed to aid Food Service Establishments in submitting cleaning records via JEA's program management software, FOG BMP. For more information on how to self-clean your grease trap, please review our best practices resource at jea.com.

- In order to submit compliance pump-out reports, the Food Service Establishment will need to have a FOG BMP profile. If your facility does not have a profile, please contact JEA at FOG@jea.com to have one created for you.
- If you already have a FOG BMP profile, please go to <u>fogbmp.com</u> and log in to your account.



 You may have to set up your account if it's your first time using the program. If so, follow the step-by-step instructions within the program. Once completed, you will be directed to your store's dashboard. It will look similar to below. Select GSD Cleaning Log.


























Select Add New Cleaning Record.



The program will auto-populate most of the information for your facility. You will need
to include information in the highlighted fields. For device condition, please indicate
"Un-Satisfactory" if you determine that the trap needs repair. Please estimate the
gallons removed.



 Self-cleaners are required to take time-stamped photos of their empty trap after cleanings to prove that the job was completed effectively. Failure to provide pictures voids the cleaning record.



 Enter the name of the person responsible for the pump-out, include the date, and sign the cleaning record certification statement by selecting the blue button below the signature box. Once signed, submit the cleaning record by selecting the Save button.

