

# STANDARDS BOOK UPDATES

## I. UPDATES 2018

DATE – UPDATED BY

1/19/18 – PARKTA

- In Chapter “Secondary”
  - On pg. 4of22 the Table has been changed to add BOXSP003
- In Chapter “System Protection”
  - The tables on pg. 4of14 and 5of14 were removed
  - The right two columns were removed from table 1 on pg. 4of14  
Along with the corresponding verbiage in III.1.3.
  - Removed II.1.1. “Overhead Laterals on Private Property” from pg. 2of14
  - Removed II.1.2.2. under “Underground Laterals” from pg. 2of14
  - Adjusted numbers for changes above
  - Adjusted page numbers, bring new total to 11pages
  - Added “Blank Page” to make section even numbered pages (12pg)
- In Chapter “Table of Content”
  - Adjusted to match up with changes made

1/22/18 – PARKTA

- New Section added “XI. Standards Book Updates”
- New Chapter added “Standards Book Updates” under section “1. Standards Book Updates”
- In Chapter “Standards Book Updates”
  - Added “I. Updates Starting 2018”
  - Updated chapter to reflect recent changes
  - Added “Blank Page” to make section even numbered pages (2pg)
- In Chapter “Table of Content”
  - Updated to include new section and chapter

5/30/18 – PARKTA

- In Chapter “Switching”
  - Plate UVS\*\_ on pg. 2of12 has been updated
    - Table updated to include Cabinet Sealing Plate info
    - Table Rearranged to fit to page
  - Plate UVSA\*\_ on pg. 3of12 has been updated
    - Table updated to include Cabinet Sealing Plate info
    - Table Rearranged to fit to page
    - Picture Rearranged to fit page
  - Plate UVSR\*3 on pg. 5of12 has been updated
    - Table updated to include Cabinet Sealing Plate info
    - Table Rearranged to fit to page
  - Chapter page amount increased from 12 to 14 pages
  - Plate SWCAB-SEAL with Instructions added to pg. 13of14
  - Added “Blank Page” to make chapter even numbered pages
- In Chapter “Table of Contents”
  - Updated Switching on pg. 12of16.

8/23/18 – PARKTA

- In Chapter “UG Feeding OH Systems”
  - “Blank Page” on pg. 14of14 was removed
  - Added page for new plate JE3 on pg. 14of14
  - Adjusted revised date on chapter
- In Chapter “Table of Contents”
  - Updated info on “UG Feeding OH Systems” section to reflect changes listed above.
  - Adjusted revised date

11/20/18 – PARKTA

- In Chapter “Grounding”
  - Updated “Grounding notes” to match Unit Price Contracts 8 ground rod Max
  - Adjusted revised date

11/30/18 – PARKTA

- In Chapter “UG Feeding OH Systems”
  - Updated JE3 on pg. 14of14
    - Removed note 2
    - Added 9 RECPA004 to the table
    - Labeled the picture JUNLO003
  - Adjusted revised date

## **II. UPDATES 2019**

2/25/19 – PARKTA

- In Chapter “Direct Buried Conduit”
  - Updated table under UCL9\* on pg. 4of4
    - Under plate UCL9\*7, Changed Special SCH 40 elbow to DB-60 elbow.
    - Under plate UCL9\*7, Changed angle in Description from 90 deg to 45 deg
  - Adjusted revised date
- In Chapter “Manholes”
  - Updated plate UDBP on pg. 20of22
    - Added Item IDs for multiple pump parts
  - Adjusted revised date

3/13/19 – PARKTA

- In Chapter “Direct Buried Conduit”
  - Updated title on pg. 4of4 from “UCL9\*” to “UCL4\*\_ AND UCL9\*\_ ”
  - Updated table under UCL4\*\_ AND UCL9\*\_ on pg. 4of4
    - Plate for Special DB-60 PVC was Changed to UCL4\*7 to match recent changes
    - Plate UCL9\*7 was added to SCH 40 Conduit with New Item CODEP013
  - Adjusted revised dates
- In Chapter “Table of Contents”
  - Updated info on “Direct Buried Conduit” section to reflect changes listed above.
  - Adjusted revised date

## 3/15/19 – PARKTA

- In Chapter “Manholes”
  - Added JEA IDs to table for Plate UDBP on pg. 21of22
  - Added Plate SET-10X16\*\_ to pg. 14of22
  - Removed “Blank Page” on pg. 22of22
  - Added comment on adding grounding plates to pgs. 7 through 14
  - Swapped out picture of 8X16 on pg. 12of22
  - Adjusted note 1 in plate ADJ-MH-T on pg. 19of22
  - Adjusted revised date
- In Chapter “Table of Contents”
  - Updated info on “Manholes” section to reflect changes listed above
  - Adjusted revised date

## 3/25/19 – PARKTA

- In Chapter “Manholes”
  - Added comment on poured in place collars, ADJ-MH to pgs. 7 through 14
- In Chapter “Pads”
  - Changed Note 4 for Plate UPD13, pg.12of14
  - Adjusted revised date

## 4/25/19 – PARKTA

- In Chapter “System Protection”
  - Updated pictures on pgs. 7of12
  - Adjusted revised date

## 5/20/19 – PARKTA

- In Chapter “Terminations”
  - Updated Plate on pgs. 14of20
    - Removed Bushing Well from Plate
  - Adjusted revised date

## 6/4/19 – PARKTA

- In Chapter “Transformers”
  - Corrected Plates on pgs. 9 through 17
    - Changed CNNTS003 to 004 to match Oracle
  - Adjusted revised date
- In Chapter “Manholes”
  - Corrected Plate SET-PVC-MH on pg. 6of22
    - Removed HOKCA006
  - Adjusted revised date
- In Chapter “Splices”
  - Corrected Plate UVSH\*1/0 on pg.17of20
    - Changed SPLSH002 to SPLST007
  - Adjusted revised date

## 6/5/19 – PARKTA

- In Chapter “Transformers”
  - Corrected Plates for UVGA\*\_ on pgs. 3 through 5
    - Removed CNNTS001 and CLATG001 to match Oracle
  - Reorganized tables for UVGA\*\_ on pgs. 3 through 5
    - This reduced the space the plates took up
  - Reorganized tables for UVGC\*\_ on pgs. 9 through 17
    - This reduced the space the plates took up
  - New page total is 14pgs
  - Adjusted revised date
- In Chapter “Table of Contents”
  - Corrected Transformer section on pg. 11of16
  - Adjusted revised date

## 7/26/19 – PARKTA

- In Chapter “Secondary”
  - Added to the table under Plate SERV\_BOX-\_\*\_ on pgs. 5of22
    - Added # of Services
  - Adjusted revised date

## 8/15/19 – PARKTA

- In Chapter “Pads”
  - Adjusted pictures and added notes to multiple plates about Bollards
  - Adjusted pictures and added notes to multiple plates about Clearances
  - Adjusted revised date
- In Chapter “Switching”
  - Adjusted pictures and added notes to multiple plates about Bollards
  - Adjusted pictures and added notes to multiple plates about Clearances
  - Adjusted revised date

## 8/20/19 – PARKTA

- In Chapter “Manholes”
  - Adjusted the picture under Plate SET-PVC-MH on pgs. 6of22
    - Picture now correctly represents MANHO008
  - Added note under Plate ADJ-MH-T on pg. 19of22
    - Allows for the pour of a rectangle to encompass two Manhole covers if they are within close proximity.
  - Adjusted revised date