


B51 exhaust duct/silencer replacement
Replace all between yellow lines

2017/11/16 11:45

A photograph of an industrial facility. On the left is a large, white, rectangular structure with a grid-like pattern of vertical and horizontal panels. To its right is a yellow building with a set of external stairs. A white pipe runs horizontally across the foreground. The ground is covered in dark gravel. The sky is clear and blue.

Upstream end

2017/11/16 11:45

A close-up photograph of a metal structure, possibly a ship's hull or a large container. A green fabric cover is visible on the right side. A yellow line is drawn along a metal beam, indicating a weld or replacement point. The text "Upstream end, replaced from Yellow line/weld aft to stack." is overlaid on the image. A timestamp "2017/11/16 11:46" is visible in the bottom right corner.

Upstream end, replaced from
Yellow line/weld aft to stack.

2017/11/16 11:46



Downstream end. Replace all to red line

2017/11/16 11:46

CONFINED SPACE
ENTER BY
PERMIT ONLY

A photograph of a mechanical assembly, likely a part of a large vessel or container. A vertical red line is drawn on the left side of the image, indicating a section to be replaced. The assembly consists of a metal frame with a dark, textured material (possibly a liner or insulation) attached to it. A metal plate with a circular hole is visible on the right side. The background is a light-colored, possibly painted, surface.

Downstream end. Replace all to red line

2017/11/16 11:46